





Water Meter Box Maintenance.

Step 1.
Remove Lid/Box
connecting wire with cutter.



Step 2.
Thread new wire through
holes in Box and Lid. Crimp
ferrule to close wire loop.



Step 3.
Test Lid fitment
and operation with Box.

